PureBliss Water
213 Beamer Road
Walden, NY 12586
845-778-1431

# Invoice

| DATE | INVOICE # |
|---|---|
| 5/28/2026 | 42852 |

| BILL TO | SHIP TO |
|---|---|
| Town of Gardiner<br>PO Box #1<br>Gardiner, NY 12525 | Town of Gardiner<br>Majestic Park<br>40 Murphy Ln<br>Gardiner, NY 12525 |

| TERMS | Equiptment Type |
|---|---|
| Due on receipt | DOH CL-2 system |

| QUANTITY | ITEM CODE | DESCRIPTION | PRICE EACH | AMOUNT |
|---|---|---|---|---|
| 1 | Svc | Service Call Charge Gil | 125.00 | 125.00 |
| 1 | Labor | Labor Performed $95/Hour | 95.00 | 95.00 |
| 1 | StenTube, D... | Stenner Tube #2 Replacement/Duct Bill & 1/4" line | 39.50 | 39.50 |
| 1 | M&S | Roller Housing (screw holes cracked) | 45.00 | 45.00 |
| | | changed listed items @ park building<br>the Hallet UV @ the rec building was completely broken & being held together by duct tape<br>tried multiple times to get bulb to strike but unsuccessful - UV unit needs to be replaced - should just be able to swap w/newer Hallet unit & re-use solenoid & 10" BB - quote to follow<br>rec building currently has water - water is currently jumping past UV but still being treated by softener<br>serviced softener & confirmed softener working properly | | |

Let's make one thing perfectly clear... Your Water !!!!

Total

Pure Bliss Water Treatment Systems, Inc.
1450 State Route 52
Walden, New York 12586
8457781431

# Estimate

| Date | Estimate # |
|---|---|
| 5/28/2026 | Majestic Pa |

| Name / Address |
|---|
| Town of Gardiner<br>PO Box #1<br>Gardiner, NY 12525 |

| Description | Qty | Cost | Total |
|---|---|---|---|
| Hallett UV, Model 500PN, NSF - less solenoid & 10" BB (normally $6225)<br><br>- to replace broken UV @ Rec Bldg | 1 | 5,425.00 | 5,425.00 |
| Let's make one thing perfectly clear... Your Water !!!! | | Subtotal | $5,425.00 |
| | | Sales Tax (0.00) | $0.00 |
| | | **Total** | $5,425.00 |