

ANALYTICAL REPORT

PREPARED FOR

Attn: Ms. Elizabeth Lock
Gertzen Water Management Company dba
Utility Services
10525 US Hwy 30
Wanatah, Indiana 46390

Generated 9/19/2024 7:46:29 AM

JOB DESCRIPTION

Ogden Dunes IN5264040

JOB NUMBER

500-256725-1

Eurofins Chicago

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Chicago Project Manager.

Authorization



Generated
9/19/2024 7:46:29 AM

Authorized for release by
Diana Mockler, Project Manager I
Diana.Mockler@et.eurofinsus.com
(219)252-7570

Table of Contents

Cover Page	1
Table of Contents	3
Case Narrative	4
Method Summary	5
Sample Summary	6
Client Sample Results	7
Definitions	9
QC Sample Results	10
Chronicle	11
Certification Summary	13
Chain of Custody	15
Receipt Checklists	18



Case Narrative

Client: Gertzen Water Management Company dba
Project: Ogden Dunes IN5264040

Job ID: 500-256725-1

Job ID: 500-256725-1

Eurofins Chicago

Job Narrative 500-256725-1

Receipt

The samples were received on 9/13/2024 2:02 PM. Unless otherwise noted below, the samples arrived in good condition, and where required, properly preserved and on ice. The temperature of the cooler at receipt was 4.8° C.

Metals

No analytical or quality issues were noted, other than those described in the Definitions/Glossary page.

Eurofins Chicago

Method Summary

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EA SB

Protocol References:

EPA = US Environmental Protection Agency

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

1
2
3
4
5
6
7
8
9
10
11
12

Sample Summary

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
500-256725-1	10 Chrismar Rd	Water	09/12/24 16:15	09/13/24 14:02
500-256725-2	9 Beach Ln	Water	09/12/24 16:15	09/13/24 14:02
500-256725-3	72 Ski Hill Pl	Water	09/12/24 16:15	09/13/24 14:02
500-256725-4	79 Ski Hill Pl	Water	09/12/24 16:15	09/13/24 14:02
500-256725-5	81 Hillcrest	Water	09/12/24 16:15	09/13/24 14:02
500-256725-6	156 Shores Dr	Water	09/12/24 16:15	09/13/24 14:02
500-256725-7	63 Ogden Rd	Water	09/12/24 16:15	09/13/24 14:02
500-256725-8	Fire Station	Water	09/12/24 16:15	09/13/24 14:02
500-256725-9	17 Summit	Water	09/12/24 16:15	09/13/24 14:02
500-256725-10	12 Indian Camp Tr	Water	09/12/24 16:15	09/13/24 14:02

Client Sample Results

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Client Sample ID: 10 Chrismar Rd

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-1

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0078		0.0010		mg/L			09/18/24 18:42	1
Lead	<0.50		0.50		ug/L			09/18/24 18:42	1

Client Sample ID: 9 Beach Ln

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-2

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0024		0.0010		mg/L			09/18/24 18:44	1
Lead	<0.50		0.50		ug/L			09/18/24 18:44	1

Client Sample ID: 72 Ski Hill PI

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-3

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.021		0.0010		mg/L			09/18/24 18:46	1
Lead	0.88		0.50		ug/L			09/18/24 18:46	1

Client Sample ID: 79 Ski Hill PI

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-4

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0061		0.0010		mg/L			09/18/24 18:48	1
Lead	0.57		0.50		ug/L			09/18/24 18:48	1

Client Sample ID: 81 Hillcrest

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-5

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.069		0.0010		mg/L			09/18/24 18:50	1
Lead	0.63		0.50		ug/L			09/18/24 18:50	1

Client Sample ID: 156 Shores Dr

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-6

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0053		0.0010		mg/L			09/18/24 18:56	1
Lead	<0.50		0.50		ug/L			09/18/24 18:56	1

Eurofins Chicago

Client Sample Results

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Client Sample ID: 63 Ogden Rd

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-7

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0054		0.0010		mg/L			09/18/24 18:58	1
Lead	<0.50		0.50		ug/L			09/18/24 18:58	1

Client Sample ID: Fire Station

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-8

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0066		0.0010		mg/L			09/18/24 19:00	1
Lead	<0.50		0.50		ug/L			09/18/24 19:00	1

Client Sample ID: 17 Summit

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-9

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0038		0.0010		mg/L			09/18/24 19:02	1
Lead	<0.50		0.50		ug/L			09/18/24 19:02	1

Client Sample ID: 12 Indian Camp Tr

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-10

Matrix: Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	0.0038		0.0010		mg/L			09/18/24 19:04	1
Lead	<0.50		0.50		ug/L			09/18/24 19:04	1

Definitions/Glossary

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Qualifiers

Metals

Qualifier	Qualifier Description
J	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

QC Sample Results

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: MB 810-115433/12

Matrix: Water

Analysis Batch: 115433

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	<0.0010		0.0010		mg/L			09/18/24 13:40	1
Lead	<0.50		0.50		ug/L			09/18/24 13:40	1

Lab Sample ID: MB 810-115433/162

Matrix: Water

Analysis Batch: 115433

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Copper	<0.0010		0.0010		mg/L			09/18/24 18:38	1
Lead	<0.50		0.50		ug/L			09/18/24 18:38	1

Lab Sample ID: LCS 810-115433/163

Matrix: Water

Analysis Batch: 115433

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Copper	0.0500	0.0538		mg/L		108	85 - 115
Lead	50.0	53.9		ug/L		108	85 - 115

Lab Sample ID: LLCS 810-115433/11

Matrix: Water

Analysis Batch: 115433

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Copper	0.000300	<0.00033		mg/L		88	50 - 150
Lead	0.300	0.298	J	ug/L		99	50 - 150

Lab Sample ID: 500-256725-5 MS

Matrix: Water

Analysis Batch: 115433

Client Sample ID: 81 Hillcrest

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits
Copper	0.069		0.0500	0.119		mg/L		100	70 - 130
Lead	0.63		50.0	60.2		ug/L		119	70 - 130

Lab Sample ID: 500-256725-5 MSD

Matrix: Water

Analysis Batch: 115433

Client Sample ID: 81 Hillcrest

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Copper	0.069		0.0500	0.121		mg/L		105	70 - 130	2	20
Lead	0.63		50.0	61.6		ug/L		122	70 - 130	2	20

Lab Chronicle

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Client Sample ID: 10 Chrismar Rd

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-1

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:42

Client Sample ID: 9 Beach Ln

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-2

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:44

Client Sample ID: 72 Ski Hill Pl

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-3

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:46

Client Sample ID: 79 Ski Hill Pl

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-4

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:48

Client Sample ID: 81 Hillcrest

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-5

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:50

Client Sample ID: 156 Shores Dr

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-6

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:56

Client Sample ID: 63 Ogden Rd

Date Collected: 09/12/24 16:15

Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-7

Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 18:58

Eurofins Chicago

Lab Chronicle

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Client Sample ID: Fire Station
Date Collected: 09/12/24 16:15
Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-8
Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 19:00

Client Sample ID: 17 Summit
Date Collected: 09/12/24 16:15
Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-9
Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 19:02

Client Sample ID: 12 Indian Camp Tr
Date Collected: 09/12/24 16:15
Date Received: 09/13/24 14:02

Lab Sample ID: 500-256725-10
Matrix: Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	115433	NB	EA SB	09/18/24 19:04

Laboratory References:
EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Accreditation/Certification Summary

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Laboratory: Eurofins Eaton Analytical South Bend

All accreditations/certifications held by this laboratory are listed. Not all accreditations/certifications are applicable to this report.

Authority	Program	Identification Number	Expiration Date
A2LA	ISO/IEC 17025	5794.01	07-31-26
Alabama	State	40700	06-30-25
Alaska	State	IN00035	06-30-25
Arizona	State	AZ0432	07-26-25
Arkansas (DW)	State	EPA IN00035	06-30-25
California	State	2920	06-30-25
Colorado	State	IN00035	02-28-25
Connecticut	State	PH-0132	03-31-26
Delaware (DW)	State	IN00035	06-30-25
Florida	NELAP	E87775	06-30-25
Georgia (DW)	State	929	06-30-25
Guam	State	23-011R	07-15-25
Hawaii	State	IN035	06-30-25
Idaho (DW)	State	IN00035	12-31-24
IL Dept. of Public Health (Micro)	State	17767	06-30-25
Illinois	NELAP	200001	09-19-24
Indiana	State	C-71-01	12-31-25
Indiana (Micro)	State	M-76-07	12-31-25
Iowa	State	IA Lab #098	11-01-25
Kansas	NELAP	E-10233	10-31-24
Kentucky (DW)	State	KY90056	12-31-24
Louisiana (DW)	State	LA014	12-31-24
Maine	State	IN00035	05-01-25
Maryland	State	209	06-30-25
Massachusetts	State	M-IN035	06-30-25
MI - RadChem Recognition	State	9926	03-22-25
Michigan	State	9926	03-22-25
Minnesota	NELAP	1989807	12-31-24
Mississippi	State	IN00035	06-30-25
Missouri	State	880	09-30-27
Montana (DW)	State	CERT0026	01-01-25
Nebraska	State	NE-OS-05-04	06-30-25
Nevada	State	IN000352024-01	07-31-25
New Hampshire	NELAP	2124	11-05-24
New Jersey	NELAP	IN598	06-30-25
New Mexico	State	IN00035	06-30-25
New York	NELAP	11398	04-01-25
North Carolina (DW)	State	18700	07-31-25
North Dakota	State	R-035	06-30-24 *
Northern Mariana Islands (DW)	State	IN00035	06-30-25
Ohio	State	87775	06-30-25
Oklahoma	NELAP	D9508	12-31-24
Oregon	NELAP	4156	09-16-25
Pennsylvania	NELAP	68-00466	04-30-25
Puerto Rico	State	IN00035	04-01-25
Rhode Island	State	LAO00343	12-30-24
South Carolina	State	95005001	06-30-24 *
South Dakota (DW)	State	IN00035	06-30-25
Tennessee	State	TN02973	06-30-25
Texas	NELAP	T104704187-22-16	12-31-24

* Accreditation/Certification renewal pending - accreditation/certification considered valid.

Eurofins Chicago

Accreditation/Certification Summary

Client: Gertzen Water Management Company dba
Project/Site: Ogden Dunes IN5264040

Job ID: 500-256725-1

Laboratory: Eurofins Eaton Analytical South Bend (Continued)

All accreditations/certifications held by this laboratory are listed. Not all accreditations/certifications are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Texas	TCEQ Water Supply	TX207	06-30-25
USEPA UCMR 5	US Federal Programs	IN00035	12-31-25
Utah	NELAP	IN00035	07-31-25
Vermont	State	VT-8775	11-15-24
Virginia	NELAP	460275	03-14-25
Washington	State	C837	01-01-25
West Virginia (DW)	State	9927 C	01-31-25
Wisconsin	State	999766900	08-31-24 *
Wisconsin (Micro)	State	10121	12-31-24
Wyoming	State	8TMS-L	06-30-25

* Accreditation/Certification renewal pending - accreditation/certification considered valid.

Eurofins Chicago

[illegible]

Eurofins Chicago

2417 Bond Street
University Park, IL 60484
Phone: 708-534-5200 Fax: 708-534-5211

Chain of Custody Record



Environment Testing

Client Information (Sub Contract Lab)		Lab PM		Carrier Tracking No(s)		COC No		
Client Contact		Mockler, Diana J		State of Origin: Indiana		500-192624-1		
Shipping/Receiving		E-Mail: Diana.Mockler@et.eurofins.com		Page: 1 of 2				
Company: Eurofins Eaton Analytical		Accreditations Required (See note): NELAP - Illinois; State Program - Indiana		Job #		500-256725-1		
Address: 110 S Hill Street,		Due Date Requested: 9/26/2024		Analysis Requested		Preservation Codes:		
City: South Bend		TAT Requested (days):						
State, Zip: IN, 46617		PO #:						
Phone: 574-233-4777(Tel) 574-233-8207(Fax)		WO #:						
Email:		Project #:						
Project Name: Ogden Dunes IN5264040		SSOW#:						
Site:								
Sample Identification - Client ID (Lab ID)	Sample Date	Sample Time	Sample Type (C=Comp, G=grab)	Matrix (W=water, S=solid, O=soil, BT=Tissue, AA=Air)	Field Filtered Sample (Yes or No)	200.8 (MOD) Lead/Copper	Total Number of Containers	Special Instructions/Note:
10 Chrismar Rd (500-256725-1)	9/12/24	16:15 Eastern	G	Water	X	X	1	
9 Beach Ln (500-256725-2)	9/12/24	16:15 Eastern	G	Water	X	X	1	
72 Ski Hill Pl (500-256725-3)	9/12/24	16:15 Eastern	G	Water	X	X	1	
79 Ski Hill Pl (500-256725-4)	9/12/24	16:15 Eastern	G	Water	X	X	1	
81 Hillcrest (500-256725-5)	9/12/24	16:15 Eastern	G	Water	X	X	1	
156 Shores Dr (500-256725-6)	9/12/24	16:15 Eastern	G	Water	X	X	1	
63 Ogden Rd (500-256725-7)	9/12/24	16:15 Eastern	G	Water	X	X	1	
Fire Station (500-256725-8)	9/12/24	16:15 Eastern	G	Water	X	X	1	
17 Summit (500-256725-9)	9/12/24	16:15 Eastern	G	Water	X	X	1	

Note: Since laboratory accreditations are subject to change, Eurofins Chicago places the ownership of method, analyte & accreditation compliance upon our subcontract laboratories. This sample shipment is forwarded under chain-of-custody. If the laboratory does not currently maintain accreditation in the State of Origin listed above for analysis/test/matrix being analyzed, the samples must be shipped back to the Eurofins Chicago laboratory or other instructions will be provided. Any changes to accreditation status should be brought to Eurofins Chicago attention immediately. If all requested accreditations are current to date, return the signed Chain of Custody attesting to said compliance to Eurofins Chicago.

Possible Hazard Identification
Unconfirmed
Deliverable Requested: I, II, III, IV, Other (specify) Primary Deliverable Rank: 2
Special Instructions/QC Requirements:

Empty Kit Relinquished by: *[Signature]* Date: 9/16/24 0915
Relinquished by: *[Signature]* Date/Time: 9/17/24 0930 Company: *[Signature]*
Relinquished by: Date/Time: Company:
Relinquished by: Date/Time: Company:

Custody Seals Intact: ☐ Yes ☐ No
Custody Seal No.: Cooler Temperature(s) °C and Other Remarks:

Ver: 05/06/2024

Login Sample Receipt Checklist

Client: Gertzen Water Management Company dba

Job Number: 500-256725-1

Login Number: 256725

List Number: 1

Creator: Hernandez, Stephanie

List Source: Eurofins Chicago

Question	Answer	Comment
Radioactivity wasn't checked or is $\leq$ background as measured by a survey meter.	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	4.8
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is $<6\text{mm}$ (1/4").	N/A	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	

Login Sample Receipt Checklist

Client: Gertzen Water Management Company dba

Job Number: 500-256725-1

Login Number: 256725

List Number: 2

Creator: Trowbridge, Peyton

List Source: Eurofins Eaton Analytical South Bend

List Creation: 09/17/24 12:37 PM

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	True	